Hedgelawn, Smokehouse
(Hedgelawn-Kohl Smokehouse)
State Route 299, 1.2 miles west of Middletown
New Castle County
St. Georges Hundred
Middletown vicinity
Delaware

HABS No. DE-189-B

HABS DEL, 2-MIDTON, 5-B-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA
REDUCED COPIES OF MEASURED DRAWINGS

Historic American Buildings Survey National Park Service Department of the Interior Washington, DC 20013-7127 Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DEL, 2-MIDTON, 5-B-

ARCHITECTURAL DATA FORM

•	COUNTY	1	OWN OR VIC	SINTLY
DELAWARE	NEW CASTLE		MIDDLETOWN VICINITY	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			HABS NO.	
HEDGELAWN, SMOKEHOUSE			DE-189-B	
SECONDARY OR COMMON NAMES OF ST	TRUCTURE			
Hedgelawn-Kohl Smokehouse			•	
COMPLETE ADDRESS (DESCRIBE LOCAT	TION FOR RURAL SI	ES) State Rou	te 299, 1.	.2 miles west of
Middletown, St. Georges Hundre	d, Delaware			
DATE OF CONSTRUCTION (INCLUDE SO	URCE) A	RCHITECT(S) (INCLU	DE SOURCE)	
1857				
SIGNIFICANCE (ARCHITECTURAL AND The Hedgelawn smokehouse is an	HISTORICAL, INCLU	DE ORIGINAL USE OF	STRUCTUR	E)
that, at one time, was a common	n form of archit	ecture in the a	rea.	sentury rarm building
STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUE	DE STRUCTURAL SYS	STEMS) Principal	nost and r	rail construction with
corner up braces, common rafter	r and collar roo	of	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	dar conseruction with
SHAPE AND DIMENSIONS OF STRUCTUR				
Original building 12 feet 3 inc	ches by 14 feet	3 3/4 inches; s:	ingle grou	and floor room
EXTERIOR FEATURES OF NOTE				
Smokeholes present in the north	h and south wall	s, box cornice.		
INTERIOR FEATURES OF NOTE (DESCRI	IBE FLOOR PLANS, I	NOT SKETCHED)		
Some original meat hooks still	present.			
MAJOR ALTERATIONS AND ADDITIONS	WITH DATES Chi	cken coop (12 f	t. 3 in. >	c 20 ft.) added to the
south gable end in the early to	wentieth century	. Concrete floo	or install	led in the smokehouse,
1 4 6 T 6 G 1 1 1 / 1			. '	
dated 1921.				1
DRESENT CONDITION AND USE	condition - our	rently used so	o atamaga	ghad Chicken agen
DRESENT CONDITION AND USE		rently used as a		shed. Chicken coop
PRESENT CONDITION AND USE Good	own, according t			shed. Chicken coop
PRESENT CONDITION AND USE Good abandoned soon to be torn do	own, according t			shed. Chicken coop
PRESENT CONDITION AND USE Good abandoned soon to be torn do	own, according t			shed. Chicken coop
PRESENT CONDITION AND USE Good abandoned soon to be torn do	own, according t	o present owner	•	
PRESENT CONDITION AND USE Good abandoned soon to be torn do	own, according t E IG LISTING ON NATIO	o present owner	•	
PRESENT CONDITION AND USE Good abandoned — soon to be torn do OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (INCLUDIN	own, according t E IG LISTING ON NATIO	o present owner	•	
PRESENT CONDITION AND USE Good abandoned — soon to be torn do OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (INCLUDIN	own, according t E OG LISTING ON NATIO Places	o present owner	TE REGISTE	RS, ETC.)